



**Left photo:** Front of building.  
**Right top:** West Wall of building before fire. Note steel shutter near front of building.  
**Right:** West Wall after fire. Windows that need to be filled in and loose and missing bricks.



**Left:** Entire building after 1920. Note the large windows and double entry doors.



Brick façade T-11 siding to cover large windows of the bar (1920 wood construction) required by Oregon Alcohol Board.